STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	155472	A. BUILDING 01 , 02 B. WING _____	R 03/23/2012

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
HOOSIER VILLAGE	9875 CHERRYLEAF DR INDIANAPOLIS, IN 46268

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
{K 000}	INITIAL COMMENTS A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 02/06/12 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 03/23/12 Facility Number: 000548 Provider Number: 155472 AIM Number: NA Surveyor: Mark Caraher, Life Safety Code Specialist At this PSR survey, Hoosier Village was found in compliance with Requirements for Participation in Medicare, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC) and 410 IAC 16.2. The original building was surveyed with Chapter 19, Existing Health Care Occupancies. This one story facility was determined to be of Type V (111) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in resident sleeping rooms, support rooms and at smoke barrier and horizontal exit doors. The facility has a capacity of 122 and had a census of 68 at the time of this survey. Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 03/26/12.	{K 000}		
{K 000}	INITIAL COMMENTS	{K 000}		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE | TITLE | (X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	155472	A. BUILDING 01 , 02 B. WING _____	R 03/23/2012

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
HOOSIER VILLAGE	9875 CHERRYLEAF DR INDIANAPOLIS, IN 46268

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
{K 000}	Continued From page 1	{K 000}		

A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 02/06/12 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).

Survey Date: 03/23/12

Facility Number: 000548
Provider Number: 155472
AIM Number: NA

Surveyor: Mark Caraher, Life Safety Code Specialist

At this PSR survey, Hoosier Village was found in compliance with Requirements for Participation in Medicare, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC) and 410 IAC 16.2. The nurses station near resident Room 128 and Room 129 was constructed in 2010 and was surveyed with Chapter 18, New Health Care Occupancies.

The 2010 addition to the one story facility was determined to be of Type V (111) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in resident sleeping rooms, support rooms and at smoke barrier and horizontal exit doors. The facility has a capacity of 122 and had a census of 68 at the time of this survey.